

## **How to install/uninstall CA5xxA WDM mini driver**

### ***Use Installshield Install Camera:***

#### **How To Install driver:**

*Windows 98, Windows 98SE, Windows Me, Windows 2000 System:*

1. Don't plug in Camera to USB port.
2. Run "SETUP.EXE" to install CA5xxA driver.
3. Plug in Camera Kit in USB port.

#### **How To Uninstall driver:**

*Windows 98, Windows 98SE, Windows Me System:*

1. [Start] -> [Settings] -> [Control Panel]->[Add/Remove Programs] ICON ->[Install/Uninstall] PAGE to remove "CA5xxA" driver.

*Windows 2000 System:*

1. Let USB Camera still plug in USB port.
2. [Start] -> [Settings] -> [Control Panel]->[Add/Remove Programs] ICON ->[Install/Uninstall] PAGE to remove "CA5xxA" driver.
3. [Start] -> [Settings] -> [Control Panel]-> [System] ICON->[Hardware] PAGE ->[Device Manager] ->[Universal Serial Bus controllers] to remove "SPCA5xxA, Sunplus USB Camera" device.

### ***Use PlugIn Install Camera:***

#### **How To Install driver:**

*Windows 98, Windows 98SE, Windows Me, Windows 2000 System:*

1. Plug in Camera to USB port.
2. Follow the dialog to set files path step by step.

#### **How To Uninstall driver:**

*Windows 98, Windows 98SE, Windows Me System:*

1. [Start] -> [Settings] -> [Control Panel]->[Add/Remove Programs] ICON ->[Install/Uninstall] PAGE to remove "Sunplus CA5xxA Camera" driver.
2. Delete 'C:\Windows\Inf\Other' 3 about CA5xx information files.

*Windows 2000 System:*

1. Let USB Camera still plug in USB port.
2. [Start] -> [Settings] -> [Control Panel]->[Add/Remove Programs] ICON ->[Install/Uninstall] PAGE to remove "Sunplus CA5xxA Camera" driver.
3. [Start] -> [Settings] -> [Control Panel]-> [System] ICON->[Hardware] PAGE ->[Device Manager]

->[Universal Serial Bus controllers] to remove “SPCA5xxA, Sunplus USB Camera” device.

4. Search files for “oem\*.\*” on “DISK C:” and delete all files of “oem\*.inf” and “oem\*.pnf” on “C:\WINDOWS\INF”.